NOTES:

SYM

- 1. THIS IS A UHV PART, ELECTROPOLISHING IS NEEDED BEFORE WELDING. PRIOR TO ELECTRO-POLISHING, THE PART MUST GO THROUGH A MULTIPLE STEP CLEANING PROCESS INVOLVING DEGREASING, WASHING AND DRY NITROGEN BLOW DOWN.
- 2. KEEP THE PART CLEAN, AND WRAP FOR UHV PACKING WITH ALUMINUM FOIL.
- 3. WHEN MACHINING VACUUM PARTS, USE OF SILICONE AND SULPHUR-BASED CUTTING FLUIDS IS PROHIBITED. USE ONE OF THE FOLLOWING:
 - A) CIMCOOL 5 STAR 49
 - B) TRIM SOL
- 4. ALL DIMENSIONS WITH [] ARE MILLIMETERS
 AND FOR REF ONLY

CHANGE DESCRIPTION

REVISIONS



